## **Manhole Inspection Summary** Manhole # S09OO 052MH of 3 Printed On: 9/30/2009 Page 1 Inspection ✓ Is Incomplete Rating: Record Plat: 0900 Node: **052** Status: Not Found Insp Date: 8/7/09 9:35 AM **Incomplete Comments** Crew: ADS2 Cannot Access - Buried - Manhole Existing Confirmed by Inspector: ADS2 **As-built** Firm: ADS Cross Street: N HILTON ST Location Address: BEHIND 3300 PIEDMONT AVE Manhole Type: Location: Alley **Ground Conditions:** Prev. Rehab Weather: Dry Subject To Ponding: None Comments CNL SEE PICTURE OF 0900 052 LOCATION AS PER MAP Diameter: (in.) Dist A/B Grade: Cover Shape: (in.) Length: (in.) Type: Sanitary Condition: Cover Material: Cast Iron Properties: Bolted Vented ☐ Water Tight ☐ Water Tight Insert **Frame** Offset: (in.) Condition: Sound Cracked Leaks **Chimney / Frame Adjustment** Exists Material: Parged Height: (in.) Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated Infiltration: None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall Corbel Material: Parged Type: Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated Infiltration: None Joint ☐ Cracks Mortar ☐ Roots ☐ Wall Barrel Material: ☐ Parged (in.) Length: Shape: Diameter: (in.) Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated Infiltration: None Joint Cracks Mortar Roots Wall **Bench** ☐ Exists Material: ☐ Parged Condition: Sound Cracked Root Intrusion ☐ Deteriorated ☐ Leaks Debris Channel Material: Parged Channel Exposure: Fully Open Junc Dist: 0 nearest .5 ft. Azimuth: Condition: Sound Cracked Root Intrusion ☐ Deteriorated ☐ Leaks Debris

Count:

Steps

Surcharge

Missing:

☐ Evidence Of Surcharge

Corroded

Depth:

(ft.) Active Surcharge Present

## **Manhole Inspection Summary**

## Manhole # \$0900\_052MH

Printed On: 9/30/2009 Page 2 of 3

LOCATION OF O9OO 52 AS PER MAP CNL DNE



## **Manhole Inspection Summary**

Manhole # \$0900\_052MH

Printed On: 9/30/2009 Page 3 of 3